

Oil Field Environmental Incident Summary

Incident: 20141008162034 **Date/Time of Notice:** 10/08/2014 16:20

Responsible Party: CITATION OIL & GAS CORP.

Well Operator: CITATION OIL & GAS CORP.

Well Name: LITTLE MISSOURI 22-9

Field Name: LITTLE MISSOURI

Well File #: 13644

Date Incident: 10/6/2014 **Time Incident:** 04:15

Facility ID Number:

County: BOWMAN

Twp: 129

Rng: 106

Sec: 9

Qtr:

Location Description:

Submitted By: Martha Smith

Received By:

Contact Person: Martha Smith
14077 CUTTEN ROAD
PO BOX 690688
HOUSTON, TX 77269-0688

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: Unknown

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil					42	barrels
Brine					3	barrels
Other	65	Barrels				

Description of Other Released Contaminant:

65 bbls total of oil & water spilled

Inspected:

Written Report Received: 10/29/2014

Clean Up Concluded: 10/20/2014

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

Some oil sprayed out of treater onto pasture land (oil did not soak into ground, just a mist on the grass). Some oil did run along side of location along fence area bordering pasture land. Currently sucking up all fluid.

Action Taken or Planned:

Shut well in, bleed pressure of treater. Drain treater. Will suck up all fluid and put back into water or oil tank. The contaminated soil will be scooped up and taken to a certified land fill. Replace corroded nipple.

Wastes Disposal Location: Certified Land fill

Agencies Involved:**Updates**

Date: 10/8/2014 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, a treater leak released 65 barrels of oil and water with a spray onto pasture land and alongside the border of the pad and fence. Followup is necessary.

Date: 12/15/2015 **Status:** Inspection

Author: Cooper, Mike

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrive on site 10:10 a.m. 23 degrees, Wind 5-10 mph SE. Snow cover is apparent on site. No visible Contam present. Searched for contamination manually. Did notice potential bare spots within the field no less than 20 feet from the treaters and flare pit. Further follow-up is needed to check for healthy vegetative growth in the spring or fall.

Date: 6/13/2016 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

6/13/2016 at 17:30, on location. Checked bare spot near treater; it appears to just be erosion from the berm around the treater. No visible staining. Beyond the areas that appear to be affected by erosion, vegetation is visible and appears unstressed. No further follow-up required at this time.